

FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS Interference Testing PLAYAS GPS 15-01 08-11 June, 2015 Lordsburg, NM

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

- A. Location: Centered at 315755N1083113W or the SSO VORTAC 105 degree radial at 042NM.
- B. Dates and times:

08 JUN 15	0300Z - 0700Z	2100Z - 2230Z
09 JUN 15	0300Z - 0500Z	
10 JUN 15	0300Z - 0700Z	2100Z - 2230Z
11 JUN 15	1900Z - 2100Z	

C. NOTAM INFO: NAV (PLAYAS GPS 15-01) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVAILABLE WITHIN A 350NM RADIUS CENTERED AT 315755N1083113W (SSO 105042) FL400-UNL DECREASING IN AREA WITH A DECREASE IN ALTITUDE DEFINED AS:

319NM RADIUS AT FL250, 250NM RADIUS AT 10000FT, 209NM RADIUS AT 4000FT AGL, 171NM RADIUS AT 50FT AGL.

D. Pilots are encouraged to report anomalies only when ATC assistance is required.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

